

Wenzhou Binyang Auto Electrical Appliance Co., Ltd







Tel:0086-577-65272716 65277662



Fax:0086-577-65270156

website: <http://www.binyang.cn>

Email: by@chinadianhuan.com

GM SERIES

| B&Y NUMBER | PICTURE | BASIC PARAMETER | OEM | REF NUMBER | APPLICATION | PRODUCTION YEAR(mm/yy) |
|------------|---|-----------------------------------|--------------------------------|---|--------------------|---|
| QDJ1245 |  | 12v/1.2kw Z:T9 Rotation:CW | A162 9208 9899 | | BUICK SAIL | |
| QDJ1218 |  | 12v/1.4kw Z:T9 Rotation:CW | LESTER:6481 WAI:2-1814-DR-2 | Delco: 9000833, 9000847, 9000859 | BUICK CHEVROLET | (2000-97) Buick Century 3.1L (2001-98) Chevrolet Cavalier 2.2L (2000-97) Chevrolet Impala, Monte Carlo, Venture 3.4L (2000-97) Chevrolet Lumina, Malibu, Monte Carlo 3.1L (2001-98) Chevrolet S, T Series Pickup, GMC Sonoma 2.2L (2000) Isuzu Hombre 2.2L |
| QDJ1219 |  | 12v/1.5kw Z:T11 Rotation:CW | LESTER:6484 WAI:2-1922-DR-2 | Delco: 9000836 9000857 41060-2F525 41060-BM525 | BUICK CHEVROLET | (2001-98) Buick Lesabre 3.8L (2001-98) Buick Park Avenue 3.8L wo/ Supercharger (2000-98) Buick Regal 3.8L wo/ Supercharger (2001-98) Chevrolet Camaro 3.8L (2000) Chevrolet Impala 3.8L (1999-98) Chevrolet Lumina 3.8L |
| QDJ1220 |  | 12v/1.5kw Z:T11 Rotation:CW | LESTER:6489 WAI:2-2054-DR-2 | Delco 9000842, 9000854, 12563908 | BUICK CHEVROLET | (2001-99) Chevrolet Silverado, GMC Sierra 4.8L, 5.3L (2001-00) Chevrolet Suburban, GMC Yukon XL 5.3L (2001-00) Chevrolet Tahoe, GMC Yukon 4.8L, 5.3L |
| QDJ1222 |  | 12v/1.6kw Z:T9 Rotation:CW | LESTER:6491 WAI:2-2110-DR-2 | Delco 8000058, 9000868, 9000901, 12579131, | BUICK | ISUZU 04.1986-12.1990 05.1984-07.1989 JAGUA 06.1972-09.1973 MAN01.1994-12.1995 |
| QDJ1227 |  | 12v/1.5kw Z:T11 Rotation:CW | LESTER:6485 WAI:2-1954-DR-2 | Delco 9000841, 9000858, 12563176, 12563828 810465-462-0 | BUICK | (2000-99) Chevrolet Astro, Blazer 4.3L (2000-99) Chevrolet & GMC G1500, G2500 4.3L (2000-98) Chevrolet S, T Series 4.3L (2000-99) GMC Jimmy, Safari, Sierra 4.3L |

| | | | | | | |
|-----------------------|---|--|--|--|--|---|
| <p>QDJ1226</p> |  | <p>12v/1.7kw Z:T11 Rotation: CW</p> | <p>LESTER:6449 WAI:2-1690-DR-2</p> | <p>Delco 9000786, 9000860, 9000899</p> | <p>CADILLAC</p> | <p>(1998-94) Chev. Blazer 4.3L, 5.7L (2001-94) Chev. C, K Series; GMC Sierra 5.0L, 5.7L, 7.4L, 8.1L (2001-94) Chev., GMC G Series 5.0L, 5.7L, (1999-94) Chev., GMC P Series Van 4.3L, (1998-96) Chev. S, T Series 4.3L; GMC Jimmy, Sonoma 4.3L (2001-99) Chev. Silverado 6.0L, 8.1L</p> |
| <p>QDJ1361</p> |  | <p>12v/1.4kw Z:T11 Rotation: CW</p> | <p>LESTER:17880 WAI: 2-2548-ND</p> | <p>GM 12567709 Nippondenso 428000-046</p> | <p>Chevrolet Avalanche</p> | <p>(2006-03) Chevrolet Avalanche, Silverado, Suburban 8.1L (2006-03) GMC Sierra, Yukon XL 8.1L</p> |